

2016 Nissan Rogue

5N1AT2MV8GC878423

Odometer: 24,582 km

1 Confirmed Code

P2096 Post Catalyst Fuel Trim System Too Lean Bank 1

1 Pending Code

P2096 Post Catalyst Fuel Trim System Too Lean Bank 1

1 Permanent Code

P2096 Post Catalyst Fuel Trim System Too Lean Bank 1

3 AUTO BACK DOOR Codes

B2426- Spindle sensor left-hand : No Sub Type Information

00

CONFIRMED

B2427- Spindle sensor right-hand : No Sub Type Information

00

CONFIRMED

B2409- Half latch switch : No Sub Type Information

00

CONFIRMED

1 Body Control Module Code

B2562- Low voltage : No Sub Type Information

00

CONFIRMED

3 MULTI Audio Visual (MULTI AV) Codes

U1000- CAN communication circuit : General Electrical Failure

01

CONFIRMED

U12AA- Configuration Error : General Signal Failure

02

CONFIRMED

U12B0- Supply Of The Battery Voltage Less Than 9V Continued For 20 Seconds. : Circuit
16 Voltage Below Threshold

CONFIRMED

1 ALL MODE ALL WHEEL DRIVE / 4-WHEEL DRIVE Code

P181B- Incomplete self shut : General Electrical Failure

01

CONFIRMED

1 IPDM E/R Code

U1000- CAN communication circuit : General Electrical Failure

01

CONFIRMED

3 AIRBAG Codes

B00A0- Occupant Classification System : No Sub Type Information

00

CONFIRMED

B142A- Ignition Voltage : Circuit Voltage Below Threshold

16

CONFIRMED

B00A0- Occupant Classification System : Erratic

8F

CONFIRMED

2 Intelligent cruise control (ICC) / Advanced Driver Assist

U1000- CAN communication circuit : General Electrical Failure

01

CONFIRMED

C1A01- Power supply circuit : Circuit Voltage Below Threshold

16

CONFIRMED

1 Around View Monitor Code

U1000- CAN communication circuit : General Electrical Failure

01

CONFIRMED

2 SIDE RADAR RIGHT Codes

C1B55- SOW RADAR STAIN : No Sub Type Information

00

CONFIRMED

U1000- CAN communication circuit : General Electrical Failure

01

CONFIRMED

1 ENGINE Control Module Code

P2096 Post Catalyst Fuel Trim System Too Lean Bank 1

HISTORY

Disclaimer: This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.