

# Full Diagnostic Report

Customer Name: N/A

Technician Name: N/A

Time: 09/29/2022 16:15:56

Shop Name: N/A	Telephone: N/A
SN: 960659902091	Email: N/A
Service Fee: USD	Repair Order No: N/A
Address:	City: N/A
State: N/A	Country or region: N/A
Zip Code: N/A	Notes: N/A

Make: OPEL	Model: Astra_H
Year: 2005	Displacement: N/A
████████████████████	████████████████
████████████████████	Vehicle Software Version: V42.80

## Pre Scan

09/29/2022 16:15:56

System(17)	Status(18)
Engine	Fault   4
ABS/TC/ESP ECU (Electronic Control Unit)	Fault   2
CIM (Steering Column Module)	Fault   1
ATW (Anti Theft Warning System)	Fault   1
REC (Rear Electrical Centre)	Fault   1
UEC (Underhood Electrical Centre)	Fault   1
IC (Instrument Cluster)	Fault   1
CDL (Central Door Lock)	Fault   1

XL/TIS (Exterior Lighting/Turn Indicator System)	Fault   1
IMMO (Immobiliser)	Fault   1
IL (Interior Lighting)	Fault   1
W&W (Wipers/Washer)	Fault   1
EHU (Entertainment Head Unit)	Fault   1
DIS (Info Display TID,BID,GID,CID)	Fault   1
EPS (Electric Power Steering)	No Fault
SRS (Supplemental Inflatable Restraint System)	No Fault
IPC (Instrument Control Unit)	No Fault

## DTC

System	Code	Description	Status
Engine	P0340-00	Camshaft Position Sensor Circuit Malfunction	Not Present
Engine	P1116-06	Coolant Thermostat Valve Circuit Low Voltage	Invalid
Engine	P1614-50	Wrong Transponder Key	Invalid
Engine	U2103-00	CAN-Bus Node no Communication	Invalid
ABS/TC/ESP ECU (Electronic Control Unit)	C0800	System Voltage High/Low Voltage	Not Present
ABS/TC/ESP ECU (Electronic Control Unit)	U2100-C	CAN-Bus Communication Malfunction	Present
CIM (Steering Column Module)	U2100-C	CAN-Bus Communication Malfunction	Not Present
ATW (Anti Theft Warning System)	U2139-00	CAN-Bus No Communication With CIM (Steering Column Module)	Not Present
REC (Rear Electrical Centre)	U2139	Invalid Signal From CIM (Steering Column Module)	Not Present
UEC (Underhood Electrical Centre)	B2575	Left Xenon Lamp Malfunction Or Left Low Beam Circuit High/Low Voltage	Not Present

IC (Instrument Cluster)	B2575-05	Headlamp Control Circuit High Voltage	Not Present
CDL (Central Door Lock)	B2575-05	Headlamp Control Circuit High Voltage	Not Present
XL/TIS (Exterior Lighting/Turn Indicator System)	B2575-05	Headlamp Control Circuit High Voltage	Not Present
IMMO (Immobiliser)	B2575-05	Headlamp Control Circuit High Voltage	Not Present
IL (Interior Lighting)	B2575-05	Headlamp Control Circuit High Voltage	Not Present
W&W (Wipers/Washer)	B2575-05	Headlamp Control Circuit High Voltage	Not Present
EHU (Entertainment Head Unit)	U2206-00	CAN-Bus No Communication With DIS (Display)	Not Present
DIS (Info Display TID,BID,GID,CID)	U2201-00	CAN-Bus No Communication With EHU (Entertainment Head Unit)	Not Present

Scan the report QR code to share the report

