

Shop Name: costello repair

Vehicle information

GM 2003 Cadillac

VIN: 1G6DM57N530162721

Diagnostics time: 2022/04/24 14:23

Mileage: 120660Miles

Path: Diagnosis > Auto scan >

Status report

System name	DTC counts	Status
Powertrain	1	Fault
DRP/ABS/TCS	5	Fault
Supplemental inflatable restraint	5	Fault
Instrument panel cluster	2	Fault
Amplifier (Bose)	5	Fault
Amplifier (Delco)	5	Fault
Climate control panel	4	Fault
Dash integration module	5	Fault
Driver door switch	0	Pass
Driver door module	6	Fault
Passenger door module	5	Fault
Left rear door module	3	Fault
Right rear door module	3	Fault
Memory seat module	6	Fault
Remote function actuation	3	Fault
Vehicle theft deterrent	2	Fault
Radio	4	Fault
OnStar	3	Fault

Rear integration module	1	Fault
Diagnostic circuit check	0	Pass

1. Powertrain — (1)

1.1. P0102	Mass Air Flow (MAF) sensor circuit low voltage
	DTC status:Current DTC
	Last test: Not ran
	This ignition: Not ran
	Since cleared:Failed

2. DRP/ABS/TCS — (5)

2.1. C1226	Right front wheel - excessive wheel speed variation
	DTC status:History DTC
2.2. C1276	Delivered torque signal circuit malfunction
	DTC status:History DTC
2.3. C1278	TCS temporarily inhibited by PCM
	DTC status:History DTC
2.4. C1298	PCM class 2 serial data link malfunction
	DTC status:History DTC
2.5. U1016	Lost communications with PCM
	DTC status:History DTC

3. Supplemental inflatable restraint — (5)

3.1. B0029	Right front side deployment loop open
	DTC status:History DTC
	Last test: Passed
	Since cleared:Passed
	History
3.2. U1000	Class 2 data link malfunction
	DTC status:History DTC
	Last test: Passed
	Since cleared:Not run/fail
	History
3.3. U1016	Lost communications with ECM/PCM/Vehicle Control Module (VCM)
	DTC status:History DTC
	Last test: Passed
	Since cleared:Passed
	History
3.4. U1040	Lost communications with Electronic Brake Control Module (EBCM)

DTC status:History DTC
Last test: Passed
Since cleared:Passed

History

3.5. U1096

Lost communications with Instrument Panel Cluster (IPC) control module

DTC status:History DTC
Last test: Passed
Since cleared:Passed

History

4. Instrument panel cluster — (2)

4.1. B1327

Device power 1 circuit low

DTC status:History DTC

4.2. U1040

Lost communications with ABS/TCS

DTC status:History DTC

5. Amplifier (Bose) — (5)

5.1. B1004

Keep Alive Memory (KAM) reset

DTC status:History DTC

5.2. B1327

Device power 1 circuit low

DTC status:History DTC

5.3. U1000

Class 2 data link malfunction

DTC status:History DTC

5.4. U1164

Lost communications with Driver Door Switch (DDS)

DTC status:History DTC

5.5. U1016

Lost communications with PCM

DTC status:History DTC

6. Amplifier (Delco) — (5)

6.1. B1004

Keep Alive Memory (KAM) reset

DTC status:History DTC

6.2. B1327

Device power 1 circuit low

DTC status:History DTC

6.3. U1000

Class 2 data link malfunction

DTC status:History DTC

6.4. U1164

Lost communications with Driver Door Switch (DDS)

DTC status:History DTC

6.5. U1016

Lost communications with PCM

DTC status:History DTC

7. Climate control panel — (4)

7.1. B1004	Keep Alive Memory (KAM) reset DTC status:History DTC
7.2. B1327	Device power 1 circuit low DTC status:History DTC
7.3. U1000	Class 2 data link malfunction DTC status:History DTC
7.4. U1016	Lost communications with PCM DTC status:History DTC

8. Dash integration module — (5)

8.1. B1004	Keep Alive Memory (KAM) reset DTC status:History DTC
8.2. B1327	Device power 1 circuit low DTC status:History DTC
8.3. U1000	Class 2 data link malfunction DTC status:History DTC
8.4. U1016	Lost communications with PCM DTC status:History DTC
8.5. U1096	Lost communications with Instrument Panel Cluster (IPC) DTC status:History DTC

9. Driver door module — (6)

9.1. B1327	Device power 1 circuit low DTC status:History DTC
9.2. U1714	Loss of door module to window motor normal speed communication DTC status:History DTC
9.3. B3832	Window express up system/function not initialized DTC status:History DTC
9.4. U1300	Class 2 data link low DTC status:History DTC
9.5. U1000	Class 2 data link malfunction DTC status:History DTC
9.6. U1016	Lost communications with PCM DTC status:History DTC

10. Passenger door module — (5)

10.1. B1327	Device power 1 circuit low DTC status:History DTC
10.2. B3832	Window express up system/function not initialized

	DTC status:History DTC
10.3. U1300	Class 2 data link low DTC status:History DTC
10.4. U1000	Class 2 data link malfunction DTC status:History DTC
10.5. U1016	Lost communications with PCM DTC status:History DTC

11. Left rear door module —— (3)

11.1. B1327	Device power 1 circuit low DTC status:History DTC
11.2. U1000	Class 2 data link malfunction DTC status:History DTC
11.3. U1016	Lost communications with PCM DTC status:History DTC

12. Right rear door module —— (3)

12.1. B1327	Device power 1 circuit low DTC status:History DTC
12.2. U1000	Class 2 data link malfunction DTC status:History DTC
12.3. U1016	Lost communications with PCM DTC status:History DTC

13. Memory seat module —— (6)

13.1. B1826	Driver recline sensor circuit range/performance DTC status:Current DTC
13.2. B2356	Driver front vertical sensor range/performance DTC status:Current DTC
13.3. B2375	Driver seat assembly horizontal sensor DTC status:Current DTC
13.4. B1327	Device power 1 circuit low DTC status:History DTC
13.5. U1000	Class 2 data link malfunction DTC status:History DTC
13.6. U1016	Lost communications with PCM DTC status:History DTC

14. Remote function actuation —— (3)

14.1. B1327	Device power 1 circuit low
-------------	----------------------------

DTC status:History DTC

14.2. U1016 Lost communications with PCM

DTC status:History DTC

14.3. U1000 Class 2 data link malfunction

DTC status:History DTC

15. Vehicle theft deterrent —— (2)

15.1. U1000 Class 2 data link malfunction

DTC status:History DTC

15.2. U1016 Lost communications with PCM

DTC status:History DTC

16. Radio —— (4)

16.1. B1327 Device power 1 circuit low

DTC status:History DTC

16.2. U1000 Class 2 data link malfunction

DTC status:History DTC

16.3. U1096 Lost communications with Instrument Panel Cluster (IPC)

DTC status:History DTC

16.4. U1016 Lost communications with PCM

DTC status:History DTC

17. OnStar —— (3)

17.1. B2470 Cellular phone antenna circuit

DTC status:Current DTC

17.2. U1000 Class 2 data link malfunction

DTC status:History DTC

17.3. U1016 Lost communications with PCM

DTC status:History DTC

18. Rear integration module —— (1)

18.1. B1327 Device power 1 circuit low

DTC status:History DTC