

Technician _____ Date&Time: 2021-03-21 12:35:58

Customer information

Title	2004 GM Cadillac		
Year	2004	VIN:	
Make	GM	Lic Plate	
Model	Cadillac	Odometer Mileage	
Sub model	XLR	Color	
Engine			

Status

Status

Technician notes

Scan report

System	Status
HVAC control module	Fault 1
Driver position module	Fault 5
Navigation radio	Fault 3
Amplifier	Fault 2
Folding top module	Fault 7
CD changer	Fault 1
ECM	Fault 1

DTC

System	Codes	Description	Status
Engine controls	U0140:00	Lost communications with BCM	Current DTC Last test: Passed This ignition: Passed Since DTC cleared: Passed & failed History
Engine cooling	U0140:00	Lost communications with BCM	Current DTC Last test: Passed This ignition: Passed Since DTC cleared: Passed & failed History
Engine electrical	B1825	Driver recline sensor circuit malfunction	Current DTC Last test: Failed Since DTC cleared: History

Engine electrical	B1826	Please refer to vehicle service manual!	Current DTC Last test: Failed Since DTC cleared: History
Engine electrical	B2463	Navigation CD player - no disc	Current DTC Last test: Failed Since DTC cleared: History
Engine electrical	U0140:00	Lost communications with BCM	Current DTC Last test: Passed This ignition: Passed Since DTC cleared: Passed & failed History
Engine electrical	U1255	Class 2 Communication Malfunction (Serial Data Line Malfunction)	History DTC Last test: Since DTC cleared: History
Engine electrical	B2355	Driver front vertical sensor malfunction	History DTC Last test: Since DTC cleared: History
Engine electrical	U1000	Class 2 data link malfunction	History DTC Last test: Since DTC cleared: History
Engine electrical	U1024	Lost communications with TCM	History DTC Last test: Since DTC cleared: History
Engine electrical	B1310	Convertible top main movement up sensor circuit	History DTC Last test: Since DTC cleared: History
Engine electrical	B1420	Device voltage malfunction	History DTC Last test: Since DTC cleared: History
Engine electrical	B3665	Front tonneau position error	History DTC Last test: Since DTC cleared: History
Engine electrical	B3666	Rear tonneau position error	History DTC Last test: Since DTC cleared: History
Engine electrical	B3971	Folding top position sensor	History DTC Last test: Since DTC cleared: History

Engine electrical	U1000	Class 2 data link malfunction	History DTC Last test: Since DTC cleared: History
Engine electrical	U1017	Lost communications with ECM	History DTC Last test: Since DTC cleared: History
Engine electrical	U1128	Lost communications with radio	History DTC Last test: Since DTC cleared: History
Anti-lock brake system	U0140:00	Lost communications with BCM	Current DTC Last test: Passed This ignition: Passed Since DTC cleared: Passed & failed History
Anti-lock brake system	B3951:05	Right rear turn signal circuit short to battery/open	History DTC Last test: Since cleared: History
Anti-lock brake system	U2100:00	CAN bus communication	History DTC Last test: Since cleared: History
Anti-lock brake system	U2105:00	Lost communications with ECM	History DTC Last test: Since cleared: History
Anti-lock brake system	U2106:00	Lost communications with TCM	History DTC Last test: Since cleared: History
Anti-lock brake system	U2108:00	Lost communications with ABS/TCS	History DTC Last test: Since cleared: History
Anti-lock brake system	U2144:00	Lost communications with adaptive cruise control	History DTC Last test: Since cleared: History
Tire pressure monitoring	B1310	Convertible top main movement up sensor circuit	History DTC Last test: Since DTC cleared: History
Tire pressure monitoring	B1420	Device voltage malfunction	History DTC Last test: Since DTC cleared: History

Tire pressure monitoring	B3665	Front tonneau position error	History DTC Last test: Since DTC cleared: History
Tire pressure monitoring	B3666	Rear tonneau position error	History DTC Last test: Since DTC cleared: History
Tire pressure monitoring	B3971	Folding top position sensor	History DTC Last test: Since DTC cleared: History
Tire pressure monitoring	U1000	Class 2 data link malfunction	History DTC Last test: Since DTC cleared: History
Tire pressure monitoring	U1017	Lost communications with ECM	History DTC Last test: Since DTC cleared: History
Body rear end	B3951:05	Right rear turn signal circuit short to battery/open	History DTC Last test: Since cleared: History
Body rear end	U2100:00	CAN bus communication	History DTC Last test: Since cleared: History
Body rear end	U2105:00	Lost communications with ECM	History DTC Last test: Since cleared: History
Body rear end	U2106:00	Lost communications with TCM	History DTC Last test: Since cleared: History
Body rear end	U2108:00	Lost communications with ABS/TCS	History DTC Last test: Since cleared: History
Body rear end	U2144:00	Lost communications with adaptive cruise control	History DTC Last test: Since cleared: History

Instrument panel	U1000	Class 2 data link malfunction	History DTC Last test: Since DTC cleared: History
Park brake	B3951:05	Right rear turn signal circuit short to battery/open	History DTC Last test: Since cleared: History
Park brake	U2100:00	CAN bus communication	History DTC Last test: Since cleared: History
Park brake	U2105:00	Lost communications with ECM	History DTC Last test: Since cleared: History
Park brake	U2106:00	Lost communications with TCM	History DTC Last test: Since cleared: History
Park brake	U2108:00	Lost communications with ABS/TCS	History DTC Last test: Since cleared: History
Park brake	U2144:00	Lost communications with adaptive cruise control	History DTC Last test: Since cleared: History
HVAC systems - automatic	U0140:00	Lost communications with BCM	Current DTC Last test: Passed This ignition: Passed Since DTC cleared: Passed & failed History
HVAC systems - automatic	U1255	Class 2 Communication Malfunction (Serial Data Line Malfunction)	History DTC Last test: Since DTC cleared: History
Variable effort steering	B3951:05	Right rear turn signal circuit short to battery/open	History DTC Last test: Since cleared: History
Variable effort steering	U2100:00	CAN bus communication	History DTC Last test: Since cleared: History
Variable effort steering	U2105:00	Lost communications with ECM	History DTC Last test: Since cleared: History

Variable effort steering	U2106:00	Lost communications with TCM	History DTC Last test: Since cleared: History
Variable effort steering	U2108:00	Lost communications with ABS/TCS	History DTC Last test: Since cleared: History
Variable effort steering	U2144:00	Lost communications with adaptive cruise control	History DTC Last test: Since cleared: History
Steering wheel and column	B1825	Driver recline sensor circuit malfunction	Current DTC Last test: Failed Since DTC cleared: History
Steering wheel and column	B1826	Please refer to vehicle service manual!	Current DTC Last test: Failed Since DTC cleared: History
Steering wheel and column	B2355	Driver front vertical sensor malfunction	History DTC Last test: Since DTC cleared: History
Steering wheel and column	U1000	Class 2 data link malfunction	History DTC Last test: Since DTC cleared: History
Steering wheel and column	U1024	Lost communications with TCM	History DTC Last test: Since DTC cleared: History
Steering wheel and column	B3951:05	Right rear turn signal circuit short to battery/open	History DTC Last test: Since cleared: History
Steering wheel and column	U2100:00	CAN bus communication	History DTC Last test: Since cleared: History
Steering wheel and column	U2105:00	Lost communications with ECM	History DTC Last test: Since cleared: History

Steering wheel and column	U2106:00	Lost communications with TCM	History DTC Last test: Since cleared: History
Steering wheel and column	U2108:00	Lost communications with ABS/TCS	History DTC Last test: Since cleared: History
Steering wheel and column	U2144:00	Lost communications with adaptive cruise control	History DTC Last test: Since cleared: History
Cellular communication	U1000	Class 2 data link malfunction	History DTC Last test: Since DTC cleared: History
Cellular communication	U1128	Lost communications with radio	History DTC Last test: Since DTC cleared: History
Cruise control	U0140:00	Lost communications with BCM	Current DTC Last test: Passed This ignition: Passed Since DTC cleared: Passed & failed History
Cruise control	B3951:05	Right rear turn signal circuit short to battery/open	History DTC Last test: Since cleared: History
Cruise control	U2100:00	CAN bus communication	History DTC Last test: Since cleared: History
Cruise control	U2105:00	Lost communications with ECM	History DTC Last test: Since cleared: History
Cruise control	U2106:00	Lost communications with TCM	History DTC Last test: Since cleared: History
Cruise control	U2108:00	Lost communications with ABS/TCS	History DTC Last test: Since cleared: History
Cruise control	U2144:00	Lost communications with adaptive cruise control	History DTC Last test: Since cleared: History

Doors	U1000	Class 2 data link malfunction	History DTC Last test: Since DTC cleared: History
Doors	B1327	Device power 1 circuit low	History DTC Last test: Since DTC cleared: History
Doors	U1301	Class 2 data link high	History DTC Last test: Since DTC cleared: History
Entertainment	B2463	Navigation CD player - no disc	Current DTC Last test: Failed Since DTC cleared: History
Entertainment	U1000	Class 2 data link malfunction	History DTC Last test: Since DTC cleared: History
Entertainment	U1024	Lost communications with TCM	History DTC Last test: Since DTC cleared: History
Entertainment	U1128	Lost communications with radio	History DTC Last test: Since DTC cleared: History
Entertainment	B3951:05	Right rear turn signal circuit short to battery/open	History DTC Last test: Since cleared: History
Entertainment	U2100:00	CAN bus communication	History DTC Last test: Since cleared: History
Entertainment	U2105:00	Lost communications with ECM	History DTC Last test: Since cleared: History
Entertainment	U2106:00	Lost communications with TCM	History DTC Last test: Since cleared: History
Entertainment	U2108:00	Lost communications with ABS/TCS	History DTC Last test: Since cleared: History

Entertainment	U2144:00	Lost communications with adaptive cruise control	History DTC Last test: Since cleared: History
Horns	B3951:05	Right rear turn signal circuit short to battery/open	History DTC Last test: Since cleared: History
Horns	U2100:00	CAN bus communication	History DTC Last test: Since cleared: History
Horns	U2105:00	Lost communications with ECM	History DTC Last test: Since cleared: History
Horns	U2106:00	Lost communications with TCM	History DTC Last test: Since cleared: History
Horns	U2108:00	Lost communications with ABS/TCS	History DTC Last test: Since cleared: History
Horns	U2144:00	Lost communications with adaptive cruise control	History DTC Last test: Since cleared: History
Keyless entry	B1310	Convertible top main movement up sensor circuit	History DTC Last test: Since DTC cleared: History
Keyless entry	B1420	Device voltage malfunction	History DTC Last test: Since DTC cleared: History
Keyless entry	B3665	Front tonneau position error	History DTC Last test: Since DTC cleared: History
Keyless entry	B3666	Rear tonneau position error	History DTC Last test: Since DTC cleared: History

Keyless entry	B3971	Folding top position sensor	History DTC Last test:
			Since DTC cleared: History
Keyless entry	U1000	Class 2 data link malfunction	History DTC Last test:
			Since DTC cleared: History
Keyless entry	U1017	Lost communications with ECM	History DTC Last test:
			Since DTC cleared: History
Lighting systems	B3951:05	Right rear turn signal circuit short to battery/open	History DTC Last test:
			Since cleared: History
Lighting systems	U2100:00	CAN bus communication	History DTC Last test:
			Since cleared: History
Lighting systems	U2105:00	Lost communications with ECM	History DTC Last test:
			Since cleared: History
Lighting systems	U2106:00	Lost communications with TCM	History DTC Last test:
			Since cleared: History
Lighting systems	U2108:00	Lost communications with ABS/TCS	History DTC Last test:
			Since cleared: History
Lighting systems	U2144:00	Lost communications with adaptive cruise control	History DTC Last test:
			Since cleared: History
Navigation systems	B2463	Navigation CD player - no disc	Current DTC Last test: Failed
			Since DTC cleared: History
Navigation systems	U1000	Class 2 data link malfunction	History DTC Last test:
			Since DTC cleared: History

Navigation systems	U1024	Lost communications with TCM	History DTC Last test: Since DTC cleared: History
Roof	B1310	Convertible top main movement up sensor circuit	History DTC Last test: Since DTC cleared: History
Roof	B1420	Device voltage malfunction	History DTC Last test: Since DTC cleared: History
Roof	B3665	Front tonneau position error	History DTC Last test: Since DTC cleared: History
Roof	B3666	Rear tonneau position error	History DTC Last test: Since DTC cleared: History
Roof	B3971	Folding top position sensor	History DTC Last test: Since DTC cleared: History
Roof	U1000	Class 2 data link malfunction	History DTC Last test: Since DTC cleared: History
Roof	U1017	Lost communications with ECM	History DTC Last test: Since DTC cleared: History
Roof	U1000	Class 2 data link malfunction	History DTC Last test: Since DTC cleared: History
Seats	B1825	Driver recline sensor circuit malfunction	Current DTC Last test: Failed Since DTC cleared: History
Seats	B1826	Please refer to vehicle service manual!	Current DTC Last test: Failed Since DTC cleared: History

Seats	U1255	Class 2 Communication Malfunction (Serial Data Line Malfunction)	History DTC Last test: Since DTC cleared: History
Seats	B2355	Driver front vertical sensor malfunction	History DTC Last test: Since DTC cleared: History
Seats	U1000	Class 2 data link malfunction	History DTC Last test: Since DTC cleared: History
Seats	U1024	Lost communications with TCM	History DTC Last test: Since DTC cleared: History
Theft deterrent	U0140:00	Lost communications with BCM	Current DTC Last test: Passed This ignition: Passed Since DTC cleared: Passed & failed History
Theft deterrent	B3951:05	Right rear turn signal circuit short to battery/open	History DTC Last test: Since cleared: History
Theft deterrent	U2100:00	CAN bus communication	History DTC Last test: Since cleared: History
Theft deterrent	U2105:00	Lost communications with ECM	History DTC Last test: Since cleared: History
Theft deterrent	U2106:00	Lost communications with TCM	History DTC Last test: Since cleared: History
Theft deterrent	U2108:00	Lost communications with ABS/TCS	History DTC Last test: Since cleared: History
Theft deterrent	U2144:00	Lost communications with adaptive cruise control	History DTC Last test: Since cleared: History

Wipers/washer systems	B3951:05	Right rear turn signal circuit short to battery/open	History DTC Last test: Since cleared: History
Wipers/washer systems	U2100:00	CAN bus communication	History DTC Last test: Since cleared: History
Wipers/washer systems	U2105:00	Lost communications with ECM	History DTC Last test: Since cleared: History
Wipers/washer systems	U2106:00	Lost communications with TCM	History DTC Last test: Since cleared: History
Wipers/washer systems	U2108:00	Lost communications with ABS/TCS	History DTC Last test: Since cleared: History
Wipers/washer systems	U2144:00	Lost communications with adaptive cruise control	History DTC Last test: Since cleared: History
HVAC control module	U1255	Class 2 Communication Malfunction (Serial Data Line Malfunction)	DTC status:History DTC Last test: Since DTC cleared: History
Driver position module	B1826	Please refer to vehicle service manual!	DTC status:Current DTC Last test: Failed Since DTC cleared: History
Driver position module	B1825	Driver recline sensor circuit malfunction	DTC status:History DTC Last test: Since DTC cleared: History
Driver position module	B2355	Driver front vertical sensor malfunction	DTC status:History DTC Last test: Since DTC cleared: History
Driver position module	U1000	Class 2 data link malfunction	DTC status:History DTC Last test: Since DTC cleared: History

Driver position module	U1024	Lost communications with TCM	DTC status:History DTC Last test: Since DTC cleared: History
Navigation radio	B2463	Navigation CD player - no disc	DTC status:Current DTC Last test: Failed Since DTC cleared: History
Navigation radio	U1000	Class 2 data link malfunction	DTC status:History DTC Last test: Since DTC cleared: History
Navigation radio	U1024	Lost communications with TCM	DTC status:History DTC Last test: Since DTC cleared: History
Amplifier	U1000	Class 2 data link malfunction	DTC status:History DTC Last test: Since DTC cleared: History
Amplifier	U1128	Lost communications with radio	DTC status:History DTC Last test: Since DTC cleared: History
Folding top module	B1310	Convertible top main movement up sensor circuit	DTC status:History DTC Last test: Since DTC cleared: History
Folding top module	B1420	Device voltage malfunction	DTC status:History DTC Last test: Since DTC cleared: History
Folding top module	B3665	Front tonneau position error	DTC status:History DTC Last test: Since DTC cleared: History
Folding top module	B3666	Rear tonneau position error	DTC status:History DTC Last test: Since DTC cleared: History

Folding top module	B3971	Folding top position sensor	DTC status:History DTC Last test: Since DTC cleared: History
Folding top module	U1000	Class 2 data link malfunction	DTC status:History DTC Last test: Since DTC cleared: History
Folding top module	U1017	Lost communications with ECM	DTC status:History DTC Last test: Since DTC cleared: History
CD changer	U1000	Class 2 data link malfunction	DTC status:History DTC Last test: Since DTC cleared: History
ECM	U0140:00	Lost communications with BCM	DTC status:Current DTC Last test: Passed This ignition: Passed Since DTC cleared: Passed & failed History