

2002 TOYOTA Avalon

4T1BF28B42U229510

Odometer: 200,000 mi

10 Confirmed Code Codes

P0300 Random/Multiple Cylinder Misfire Detected

Confirmed

P0302 Cylinder 2 Misfire Detected

Confirmed

P0304 Cylinder 4 Misfire Detected

Confirmed

P0306 Cylinder 6 Misfire Detected

Confirmed

P0171 System Too Lean Bank 1

Confirmed

P0174 System Too Lean Bank 2

Confirmed

P1305 Igniter Circuit #2

Confirmed

P1315 Igniter Circuit #4

Confirmed

P1325 Igniter Circuit #6

Confirmed

P1354 VVT System

Confirmed

3 Pending Code Codes

P0171 System Too Lean Bank 1

Pending

P0174 System Too Lean Bank 2

Pending

P1150 Coolant Path Clog Up For Coolant Heat Storage System
Pending

0 Permanent Code Codes

10 Engine/Transmission System Codes

P0300 Random/Multiple Cylinder Misfire Detected

P0302 Cylinder 2 Misfire Detected

P0304 Cylinder 4 Misfire Detected

P0306 Cylinder 6 Misfire Detected

P0171 System Too Lean Bank 1

P0174 System Too Lean Bank 2

P1305 Igniter Circuit #2

P1315 Igniter Circuit #4

P1325 Igniter Circuit #6

P1354 VVT System

3 Airbag Codes

P0891 TCM Power Relay Sense Circuit High

P0091 Short Circuit To Ground Of Pressure Control Valve Output

C1624 Check report for description.

Disclaimer: This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.