

2012 SRX

[Report a problem with this article](#)

Subject:	Diagnostic Information for DTC P062F Set	
Models:	2012 Buick Enclave, LaCrosse, Regal, Verano	
	2012 Cadillac SRX	
	2012 Chevrolet Camaro, Equinox, Impala, Orlando, Traverse	
	2012 GMC Acadia, Terrain	
	Equipped with Engine RPO LLT, LUK, LFX, LAF, LEA, LFW or LF1	

This bulletin replaces PI0682A. Please discard PI0682A.

Some dealers may notice DTC P062F set in the ECM. This DTC may either be active or in history.

This code can falsely set during a low battery condition. This can also trigger certain HO2S heater sensor codes (P0030, P0036, P0050, P0053, P0054, P0056, P0059, P0060, P0135, P0141, P0155, P0161).

Important: Do not diagnose the HO2S heater sensor codes until the P062F has been corrected.

If only these codes are set and the vehicle is not exhibiting low battery symptoms, clear the DTCs and perform a couple of engine starts allowing the engine to run for a minute, then shut down and allow the ECM to power down, about a minute. Restart the engine. If no DTCs reset, no further action is necessary. If the DTCs reset, check the ECM power and Ground circuits, as low voltage to the ECM can cause these DTCs to set. If no issues are identified with these circuits, perform normal SI Diagnostics.

If the vehicle is experiencing low battery symptoms, perform Battery Inspection/Test per normal SI Diagnostics. Note that these DTCs can be set if the vehicle has a battery with a low state of charge due to extended storage time, etc.

Warranty Information

Note: The maintenance of new and unsold vehicle batteries is the dealer's responsibility and not considered a warrantable event.

Use Labor Operation J9999 Electrical and Powertrain Controls – Labor Only for the checking and clearing the DTC on delivered vehicles.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the



WE SUPPORT
VOLUNTARY

proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

TECHNICIAN
CERTIFICATION