



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20210426
Creation Date: 2021-04-26



2011 GM Vehicle Diagnostic Report

Technician:	Date&Time: 2021-04-26 19:58:52
License Plate: NONE	Client:
Manufacturer: GM	Client Phone Number:
Year: 2011	VIN: 1GKKVSED2BJ253422
Model: GMC Truck	Mileage: 143559Miles
Sub Model: GMC Acadia SLT 2 (AWD)	Color:
Engine:	
Path: GM>Automatic selection>2011>Light duty truck, MPV, Incomplete>GMC Truck>(D) 3.6L V6 LLT>GMC Acadia SLT 2 (AWD)>Automatic>Auto scan>	

System	Status
1. Engine control module	Fault 8
2. Transmission control module	Pass No Fault
3. Electronic brake control module	Fault 1
4. Supplemental inflatable restraint	Fault 1
5. Body control module	Pass No Fault
6. Fuel pump control module	Pass No Fault
7. Instrument panel cluster	Pass No Fault
8. Park assist module	Pass No Fault
9. Rear drive system	Pass No Fault
10. Vehicle communication interface module	Fault 1
11. Digital radio receiver	Pass No Fault
12. Liftgate module	Pass No Fault
13. Remote control door lock receiver	Pass No Fault
14. Theft deterrent module	Pass No Fault
15. Memory seat module	Pass No Fault
16. Passenger presence system	Pass No Fault
17. HVAC control module	Fault 2



18. Driver door switch	Pass No Fault
19. Passenger door switch	Pass No Fault
20. Head up display	Pass No Fault
21. Rear HVAC/RSA	Pass No Fault

DTC

1. Engine control module(8 DTCs)

Codes	Description	Status
P000B:00	Exhaust Camshaft Position (CMP) system slow response bank 1	Current DTC Last test: Failed/current This ignition: Not run Since DTC cleared: Failed
P0024:00	Exhaust Camshaft Position (CMP) system performance bank 2	Current DTC Last test: Failed/current This ignition: Not run Since DTC cleared: Failed
P0134:00	Heated Oxygen Sensor (HO2S) circuit insufficient activity (bank 1 sensor 1)	Current DTC Last test: Failed/current This ignition: Not run Since DTC cleared: Failed
P0300:00	Engine misfire detected	Current DTC Last test: Failed/current This ignition: Not run Since DTC cleared: Failed
P0306:00	Cylinder 6 misfire detected	Current DTC Last test: Failed/current This ignition: Not run Since DTC cleared: Failed
P0014:00	Exhaust Camshaft Position (CMP) system performance bank 1	Current DTC Last test: Not run This ignition: Not run Since DTC cleared: Passed & failed



P0300:00	Engine misfire detected	Current DTC Last test: Not run This ignition: Not run Since DTC cleared: Passed & failed
P0301:00	Cylinder 1 misfire detected	Current DTC Last test: Not run This ignition: Not run Since DTC cleared: Passed & failed

2. Electronic brake control module(1 DTC)

Codes	Description	Status
C0299:5A	Brake boost regulation pressure sensor plausibility failure	History DTC Last test :Passed This ignition: Passed Since DTC cleared: History

3. Supplemental inflatable restraint(1 DTC)

Codes	Description	Status
B1019:3A	Sensing and Diagnostic Module (SDM) system configuration error incorrect component installed	History DTC Last test: Passed This ignition: Passed Since cleared:Passed History

4. Vehicle communication interface module(1 DTC)

Codes	Description	Status
U0184:00	Lost communications with radio	History DTC Last test: Since cleared: History

5. HVAC control module(2 DTCs)

Codes	Description	Status
B0228:04	Recirculate position feedback circuit open	Current DTC Last test: Failed/current Since cleared: History
B0228:05	Recirculate position feedback circuit short to battery/open	History DTC Last test: Since cleared: History

Technician notes



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20210426
Creation Date: 2021-04-26



Customer's name: _____

Technician: _____

Date: _____

Notice: Please save a copy of this report for your records.