

Vehicle diagnostic report

Owner name: Summer Roberson

License #: 081jgb

Make: Chrysler

Model: Town & Country

Year: 2014

VIN: 2C4RC1BG5ER444356

Odometer: 189215 (mile)

Vehicle Software Version: V33.50

Diagnostic Application Version: V6.00.002

Test Time: 2021-10-24 18:36:33

Technician Name: Mitch Roberson

Diagnostic path: 16 PIN Connector > Automatically Search > Health Report

Diagnostic Result

Fault (2)

PCM (Powertrain Control Module) (3) Abnormal

P0017 Crankshaft/Camshaft Timing Misalignment - Bank 1 Sensor 2 Active

P000A Bank 1 Camshaft 1 Position Slow Response Pending

P000B Bank 1 Camshaft 2 Position Slow Response Pending

HVAC (Heating Ventilation Air-conditioning And Cooling)/AC (Air Conditioner) (1) Abnormal

B1058-13 Recirculation Door Control-Circuit Open Active

Normal (16)

ABS (Anti-lock Braking System) Normal

SRS (Supplemental Inflatable Restraint System - ORC) Normal

BCM (Body Control Module - TIPMCGW/FCMCGW) Normal

CCN (Cabin Compartment Node - Instrument Cluster) Normal

WCM/TPMS (Wireless Control Module - Tire) Normal

Radio Normal

HFM (Hands Free Module) Normal

DMFL (Door Module Front Left) Normal

DMFR (Door Module Front Right) Normal

DMRR (Door Module Rear Right) Normal

DMRL (Door Module Rear Left) Normal

PLGM (Power Lift Gate Module)	Normal
VES3 (Last Row Screen)	Normal
RPSDM (Right Power Sliding Door Module)	Normal
SAS (Steering Angle Sensor)	Normal
LPSDM (Left Power Sliding Door Module)	Normal

Notes: post Rocker arm replacment