1997 GMC Truck C 1500 Truck 2WD V8-5.7L VIN R Vehicle > ALL Diagnostic Trouble Codes (DTC) > Testing and Inspection > P Code Charts

5	1. Disconnect the EGR Valve electrical connector. 2. Connect a test light between the EGR Valve harness connector terminals A and E. 3. Command the EGR Position to the specified value. Is the test light ON?	100%	Go to Step 23	Go to Step 6
6	Connect a test light to a known good ground. Probe the EGR Valve harness connector terminal E. Is the test light ON?		Go to Step 7	Go to Step 13
7	Check for a faulty connection at the EGR Valve harness connector terminal A. Check for an open in the EGR Valve Control Circuit. Was a problem found?	_	Go to Step 8	Go to Step 36
8	Repair the faulty connections or open in the EGR Valve Control circuit as necessary. Refer to Wiring Repairs. Is the action complete?		Go to Step 38	_
9	Is DTC P0108 also set?	_	Go to DTC P0108 Manifold Absolute Pressure (MAP) Sensor Circuit High Voltage	Go to Step 10

1 of 2



2 of 2