

1997 GMC Truck C 1500 Truck 2WD V8-5.7L VIN R

Vehicle > ALL Diagnostic Trouble Codes (DTC) > Testing and Inspection > P Code Charts

34	<p>1. Turn the ignition switch OFF.</p> <p>2. Disconnect the C1 (Blue) VCM connector.</p> <p>3. Turn the ignition switch ON, with the engine OFF.</p> <p>4. Connect a test light to a known good ground.</p> <p>5. Probe Pin 4 of the C1 (Blue) VCM connector with proper test adapter from Connector Test Adapter kit J 35616 .</p> <p>Is the test light ON?</p>	—	Go to Step 36	Go to Step 35
35	<p>Repair open in ignition feed circuit to Pin 4 of the C1 (Blue) VCM connector.</p> <p>Refer to Wiring Repairs.</p> <p>Is the action complete?</p>	—	Go to Step 38	—
36	<p>Check for poor connections at the VCM harness connectors and repair as necessary.</p> <p>Refer to Wiring Repairs.</p> <p>Was a repair necessary?</p>	—	Go to Step 38	Go to Step 37
37	<p>Important: Program the new VCM.</p> <p>Refer to VCM Replacement/Programming.</p> <p>Replace the VCM.</p> <p>Is the action complete?</p>	—	Go to Step 38	—