

Dec 08, 2017 10:33 AM

VIN retrieved from Vehicle
VIN: 1D7HU18P17J516845
Make:Dodge Year:2007

Trouble Code P0430 triggered Freeze Frame.
Code Def: Catalyst System Efficiency Below Threshold Bank 2

PID	Description	Value
04	: Calculated Engine Load Value	: 63.9 %
05	: Engine Coolant Temperature	: 94 °C
06	: Short Term Fuel Trim Bank 1	: -3.9 %
07	: Long Term Fuel Trim Bank 1	: -0.8 %
08	: Short Term Fuel Trim Bank 2	: -2.3 %
09	: Long Term Fuel Trim Bank 2	: 0.0 %
0B	: Intake Manifold Absolute Pressure	: 74.0 kPa
0C	: Engine RPM	: 1698 rpm
0D	: Vehicle Speed	: 102 km/h
0E	: Timing Advance for #1 cylinder	: 26.0 °
0F	: Intake Air Temperature	: 3 °C
11	: Absolute Throttle Position	: 23.1 %
1E	: Auxiliary Input Status	: OFF
1F	: Run Time Since Engine Start	: 1246 seconds
2C	: Commanded EGR	: 39.6 %
2D	: EGR Error	: -9.4 %
2E	: Commanded Evaporative Purge	: 0.0 %
2F	: Fuel Level Input	: 29.8 %
33	: Barometric Pressure	: 100 kPa
42	: Control Module Voltage	: 14.793 V
43	: Absolute Load Value	: 51.4 %
44	: Commanded Equivalence Ratio	: 0.999 λ
45	: Relative Throttle Position	: 11.4 %
46	: Ambient Air Temperature	: 1 °C

Disclaimer:

This information is provided without warranty and is subject to the Terms of Use posted at www.lemurmonitors.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.

Vehicle Protocol: CAN11_500
Sensor F/W Version: OSAPI v2.39
App Version: 6.10.115

Disclaimer:

This information is provided without warranty and is subject to the Terms of Use posted at www.lemurmonitors.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.