

Shop Name:

Email:

Shop Number:

Tel:

Address:

## Vehicle information

GM 2016 Chevrolet

VIN: 1G1FB1RS5G0161686

Diagnostics time: 2022/03/04 14:55

**Mileage:**

Path: Automatic &gt; 0501 &gt; 9.7 &gt; Diagnosis &gt; Control unit &gt; Engine control module &gt; Trouble codes &gt; DTC display &gt;

## DTC display

**1. P0016:00** Crankshaft position - intake camshaft position not plausible bank 1

DTC history status : History  
Since DTC clear : Passed and failed  
Last test : Passed  
This ignition cycle : Passed  
MIL status : Requested

**2. P0016:00** Crankshaft position - intake camshaft position not plausible bank 1

DTC history status : Not history  
Since DTC clear : Passed  
Last test : Passed  
This ignition cycle : Passed  
MIL status : Not requested

**3. P0016:00** Crankshaft position - intake camshaft position not plausible bank 1

DTC history status : Not history  
Since DTC clear : Passed  
Last test : Failed current DTC  
This ignition cycle : Passed  
MIL status : Not requested

**4. P0018:00** Crankshaft position - intake camshaft position not plausible bank 2

DTC history status : History  
Since DTC clear : Passed and failed  
Last test : Passed  
This ignition cycle : Passed  
MIL status : Requested

**5. P0018:00** Crankshaft position - intake camshaft position not plausible bank 2

DTC history status : Not history  
Since DTC clear : Passed  
Last test : Passed  
This ignition cycle : Passed  
MIL status : Not requested