



Shop: Daves Garage  
 Tel:  
 Address:

Report ID: MAXIA20220821  
 Creation Date: 2022-08-21



## 2010 GM Vehicle Diagnostic Report

License Plate: 12345  
 Manufacturer: GM  
 Year: 2010  
 Model: GMC  
 Sub Model: Terrain  
 Engine:

Client: Customer  
 Phone Number:  
 VIN: 2CTFLCEWXA6276845  
 Mileage: 155828.04 mile  
 Color:  
 Status:

Path: GM>Automatic selection>2010>Light duty truck>GMC>Terrain>2.4L (LAF)>2CTFLCEWXA6276845>Not equipped>Passenger presence system (AL0)>Not equipped>8>Electric power steering (NJ0 NJ1)>Manual control single zone (C67)>Auto scan>Engine control module>Trouble codes

### DTC display

Codes	Description	Status
P0315:00	Crankshaft position system variation not learned	DTC history status : History Since DTC clear : Failed Last test : Failed current DTC This ignition cycle : Failed MIL status : Requested
P0633:00	Immobilizer key not programmed	DTC history status : History Since DTC clear : Failed Last test : Failed current DTC This ignition cycle : Failed MIL status : Not requested