

Shop Name: Dinos Repair

Address: [REDACTED], West Covina, 91790, CA

Vehicle information

VIN:

Mileage:

Diagnostics time: 2021/08/22 19:58

Path:

☒	Short term fuel trim -bank 1 ▼	-2.3	-100...99.22	%
☒	Short term fuel trim -bank 2 ▼	-2.3	-100...99.22	%
☒	Engine RPM ▼	1897	0...8000	rpm
☒	Air flow rate from mass air flow sensor ▼	62.75	0...655.35	g/s
☒	Oxygen sensor output voltage bank 1-sensor 1 ▼	0.79	0...1.275	V
☒	Oxygen sensor output voltage bank 2-sensor 1 ▼	0.57	0...1.275	V
Time:00:13/01:17 Frame:59/331 Graph merge Show all Previous frame Next frame Back				