

Shop Name: Dinos Repair

[REDACTED] West Covina, 91790, CA

Vehicle information

EOBD SAE J1850(VPW)

VIN:

Diagnostics time: 2021/08/23 05:14

Mileage:

Path: Autoscan > DTC&FFD >

Freeze frame

DTC that caused required freeze frame data storage	P0300	
Fuel system A status	CL	
Fuel system B status	CL	
Calculated load value	25.9	%
Engine coolant temperature	194.00	°F
Short term fuel trim -bank 1	7.0	%
Long term fuel trim - bank 1	6.2	%
Short term fuel trim -bank 2	2.3	%
Long term fuel trim - bank 2	6.2	%
Intake manifold absolute pressure	10.44	psi
Engine RPM	2414	rpm
Vehicle speed sensor	72.70	mph
Air flow rate from mass air flow sensor	0.13	lb/s
Absolute throttle position	30.2	%