

Shop Name: Dinos Repair

Address: 1334 South Bromley, West Covina, 91790, CA

Vehicle information

VIN:

Mileage:

Diagnostics time: 2021/08/25 19:46

Path:



☒ Short term fuel trim -bank 1 ▾	1.6	-100...99.22	%
☒ Short term fuel trim -bank 2 ▾	-0.8	-100...99.22	%
☒ Engine RPM ▾	2072	0...8000	rpm
☒ Air flow rate from mass air flow sensor ▾	76.45	0...655.35	g/s
☒ Absolute throttle position ▾	42.7	0...100	%
☒ Oxygen sensor output voltage bank 1-sensor 1 ▾	0.825	0...1.275	V
☒ Oxygen sensor output voltage bank 2-sensor 1 ▾	0.15	0...1.275	V

Time:00:39/00:43

Frame:193/209

Graph merge

☒

Show all

Previous frame

Next frame

Back