

Vehicle Diagnostic Report

The Report is created by **LAUNCH X-431**

Repair Shop

Shop Name:

Address:

Zip Code:

Telephone:

Email:

SN:976990008766

Test Time:2020-06-22 13:00:34



Vehicle Information

Year:2018

Make:EOBD

Model:Terrain

VIN:3GKALREU1JL255339

Vehicle Software Version:V22.77

Diagnostic Application Version:V66 AG



Inspection Result

EOBD 13 problems exist

1.P007D Charge Air Cooler Temperature Sensor Circuit High Bank 1	Current
2.P0113 Intake Air Temperature Sensor 1 Circuit High	Current
3.P2199 Intake Air Temperature Sensor 1/2 Correlation	Current
4.P227D Barometric Pressure Sensor C Circuit High	Current
5.P007D Charge Air Cooler Temperature Sensor Circuit High Bank 1	Pending
6.P0113 Intake Air Temperature Sensor 1 Circuit High	Pending
7.P2199 Intake Air Temperature Sensor 1/2 Correlation	Pending
8.P227B Barometric Pressure Sensor C Circuit Range/Performance	Pending
9.P227D Barometric Pressure Sensor C Circuit High	Pending
10.P227B Barometric Pressure Sensor C Circuit Range/Performance	Permanent
11.P0116 Engine Coolant Temperature Sensor 1 Circuit Range/Performance	Permanent
12.P0113 Intake Air Temperature Sensor 1 Circuit High	Permanent
13.P22A3 NOx Sensor Heater Control Circuit/Open Bank 1 Sensor 2	Permanent