Test report

Job No: 271954 **Date: 25/09/2017**

Tests Performed: ECU Testing LTD.
Customer Name: #######
Part number: ###########

Test Condition

- **Current Consumption**
- **Ignition Output**
- **Injector Outputs**
- **Internal Voltages**
- **MAP/MAF Operation**
- **Neutral Input**
- **Water Temperature Input**
- **Throttle Input**
- **Idle control output**
- **Supply Voltage Compensation**
- **Rev Limit**
- **Error code Operation**

Test Result

The results shown are valid ONLY at the Time of Test.
Intermittent problems may not have been detected.

Test 1: :
Test 1:
Test 1: : Test – PASS
Test 1:
Test 1: :

Test condition:
PASS – Bosch MEV17.4 engine ECU passed all of our tests successfully.

Root cause analysis:
N/A

Countermeasures to root cause:
N/A

Results:
PASS – Current consumption pass. Communication protocols pass. Live data and fault code operations pass. Live data for ECT and CKP pass. 5v references all present. I O functions pass. Visual inspection pass. Component and circuit testing pass.